

**Location:** US 280  
**Section:** 25

**Pavement Preservation Treatment:** FiberMat Chip Seal (89s)

**Section Information:**

Placement Date: 8/27/2015  
Emulsion/Tack Material: UNKNOWN  
Target Emulsion Rate (gal/SY): 0.34  
Calibrated Emulsion Rate (gal/SY): 0.344  
Average Verified Emulsion Rate (gal/SY): 0.378\*  
Aggregate Type: Columbus Granite, 89s  
Target Chip Rate (lb/SY): 18  
Verified Chip Rates (lb/SY): Found Below  
Milled Depth: N/A

**Left-Wheel Path:**

Placement Date: 8/27/2015  
Emulsion/Tack Material: UNKNOWN  
Target Emulsion Rate (gal/SY): 0.34  
Calibrated Emulsion Rate (gal/SY): 0.344  
Verified Emulsion Rate (gal/SY): 0.399  
Aggregate Type: Columbus Granite, 89s  
Target Chip Rate (lb/SY): 18  
Verified Chip Rate (lb/SY): 15.5

**Between-Wheel Paths:**

Placement Date: 8/27/2015  
Emulsion/Tack Material: UNKNOWN  
Target Emulsion Rate (gal/SY): 0.34  
Calibrated Emulsion Rate (gal/SY): 0.344  
Verified Emulsion Rate (gal/SY): 0.371  
Aggregate Type: Columbus Granite, 89s  
Target Chip Rate (lb/SY): N/A  
Verified Chip Rate (lb/SY): N/A

**Right-Wheel Path:**

Placement Date: 8/27/2015  
Emulsion/Tack Material: UNKNOWN  
Target Emulsion Rate (gal/SY): 0.34  
Calibrated Emulsion Rate (gal/SY): 0.344  
Verified Emulsion Rate (gal/SY): 0.363  
Aggregate Type: Columbus Granite, 89s  
Target Chip Rate (lb/SY): 18  
Verified Chip Rate (lb/SY): 16.5

**Microsurface Information:**

Placement Date: 8/27/2015  
Target Microsurface Rate (lb/SY): N/A  
Verified Microsurface Rate (lb/SY): N/A

General Notes: