

Lift 1	
<b>Location:</b>	US 280
<b>Section:</b>	27
<b>Pavement Preservation Treatment:</b>	Chip Seal (7s)
<b>Section Information:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.29
Calibrated Emulsion Rate (gal/SY):	0.314
Average Verified Emulsion Rate (gal/SY):	0.322
Aggregate Type:	Columbus Granite, 7s
Target Chip Rate (lb/SY):	23
Verified Chip Rates (lb/SY):	Found Below
Milled Depth:	N/A
<b>Left-Wheel Path:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.29
Calibrated Emulsion Rate (gal/SY):	0.314
Verified Emulsion Rate (gal/SY):	0.283
Aggregate Type:	Columbus Granite, 7s
Target Chip Rate (lb/SY):	23
Verified Chip Rate (lb/SY):	22.5
<b>Between-Wheel Paths:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.29
Calibrated Emulsion Rate (gal/SY):	0.314
Verified Emulsion Rate (gal/SY):	0.336
Aggregate Type:	Columbus Granite, 7s
Target Chip Rate (lb/SY):	N/A
Verified Chip Rate (lb/SY):	N/A
<b>Right-Wheel Path:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.29
Calibrated Emulsion Rate (gal/SY):	0.314
Verified Emulsion Rate (gal/SY):	0.346
Aggregate Type:	Columbus Granite, 7s
Target Chip Rate (lb/SY):	23
Verified Chip Rate (lb/SY):	14*
<b>Microsurface Information:</b>	
Placement Date:	8/28/2015
Target Microsurface Rate (lb/SY):	N/A
Verified Microsurface Rate (lb/SY):	N/A
General Notes:	

Lift 2	
<b>Location:</b>	US 280
<b>Section:</b>	27
<b>Pavement Preservation Treatment:</b>	Chip Seal (89s)
<b>Section Information:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.44
Calibrated Emulsion Rate (gal/SY):	N/A
Average Verified Emulsion Rate (gal/SY):	0.443
Aggregate Type:	Columbus Granite, 89s
Target Chip Rate (lb/SY):	18
Verified Chip Rates (lb/SY):	Found Below
Milled Depth:	N/A
<b>Left-Wheel Path:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.44
Calibrated Emulsion Rate (gal/SY):	N/A
Verified Emulsion Rate (gal/SY):	0.415
Aggregate Type:	Columbus Granite, 89s
Target Chip Rate (lb/SY):	18
Verified Chip Rate (lb/SY):	15
<b>Between-Wheel Paths:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.44
Calibrated Emulsion Rate (gal/SY):	N/A
Verified Emulsion Rate (gal/SY):	0.448
Aggregate Type:	Columbus Granite, 89s
Target Chip Rate (lb/SY):	N/A
Verified Chip Rate (lb/SY):	N/A
<b>Right-Wheel Path:</b>	
Placement Date:	8/28/2015
Emulsion/Tack Material:	CRS-1HP
Target Emulsion Rate (gal/SY):	0.44
Calibrated Emulsion Rate (gal/SY):	N/A
Verified Emulsion Rate (gal/SY):	0.465
Aggregate Type:	Columbus Granite, 89s
Target Chip Rate (lb/SY):	18
Verified Chip Rate (lb/SY):	16
<b>Microsurface Information:</b>	
Placement Date:	8/28/2015
Target Microsurface Rate (lb/SY):	N/A
Verified Microsurface Rate (lb/SY):	N/A
General Notes:	